GRADE




The road climbed to Fall River Pass on steep grades sometimes reaching 16%. Some early automobiles had to climb in reverse due to their weak engines and gravity-fed fuel systems. Surfacing materials washed off quickly.

TURN RADIUS




Motorists had to negotiate sixteen switchbacks with radii as tight as 20'. Some vehicles had to turn back and forth repeatedly to make the curves.

ROAD WIDTH



ELEVATION GAIN



PULLOUTS



Few pullouts were provided to allow motorists to stop; some were located on switchbacks, making the curves even more difficult.

